



Province of the
EASTERN CAPE
EDUCATION

**NATIONAL
SENIOR CERTIFICATE**

GRADE 12

SEPTEMBER 2021

**MECHANICAL TECHNOLOGY:
(FITTING AND MACHINING)
MARKING GUIDELINE**

MARKS: 200

This marking guideline consists of 14 pages.

QUESTION 1: MULTIPLE-CHOICE QUESTIONS (GENERIC)

- 1.1 C ✓
 1.2 D ✓
 1.3 D ✓
 1.4 A ✓
 1.5 B ✓
 1.6 B ✓

(6 x 1) [6]

QUESTION 2: SAFETY (GENERIC)**2.1 Safety Precautions**

- Pressure gauges must be checked and tested regularly and adjusted or replaced if any malfunctioning occurs. ✓
- Supporting pins that keep the platform at a desired height on the frame must be inspected for damage. ✓
- Check the floor for oil and apparatus for leaks. ✓
- The platform on which the workpiece rests must be rigid and square with the press cylinder. ✓

(Any 2 x 1) (2)

2.2 Product layout

✓✓ (2)

2.3 Perspex shield

is installed to shield flying objects from harming the operator's eye. ✓

(1)

2.4 2.4.1 Machine Identification

Surface grinder ✓

(1)

2.4.2 Surface grinder parts label

- A Workpiece ✓
 B Machine spindle ✓
 C Magnetic table ✓
 D Grinding wheel ✓

(4)

[10]

QUESTION 3: MATERIALS (GENERIC)

3.1 Heat treatment refers to heating and cooling of metals under controlled conditions in their solid state so as to change their properties. ✓✓ (2)

3.2 **Heat treatment properties**

PROCESS		PROPERTY
3.2.1	Hardening	Very hard, high tensile strength and brittle ✓
3.2.2	Tempering	Tough, hard ✓
3.2.3	Annealing	Soft, ductile, low tensile strength ✓
3.2.4	Normalising	Tough and machinable ✓

(4)

3.3 **Purpose of case-hardening**

- It hardens the surface. ✓
- It provides a wear resistant surface. ✓
- Strengthens core to withstand applied loads. ✓ (Any 2 x 1) (2)

3.4 **Carbon effect**

Steel with low carbon content ✓ will not respond very much to the hardening process. ✓ (2)

3.5 **Workshop tests on materials**

Sound test ✓

Bend test ✓

Filing test

Machining test



(Any 2 x 1) (2)

3.6 **Reasons for annealing**

- To relieve internal stresses that may have been set up during other processes. ✓
- To soften them in order to facilitate the machining processes. ✓
- To make material ductile.
- Refine their grain structures.
- Reduce brittleness (Any 2 x 1) (2)

[14]

QUESTION 4: MULTIPLE-CHOICE QUESTIONS (SPECIFIC)

- 4.1 A ✓
 4.2 D ✓
 4.3 A ✓
 4.4 A ✓
 4.5 A ✓
 4.6 B ✓
 4.7 A ✓
 4.8 C ✓
 4.9 D ✓
 4.10 B ✓
 4.11 B ✓
 4.12 A ✓
 4.13 A ✓
 4.14 B ✓

(14 x 1) [14]

QUESTION 5: TERMINOLOGY (LATHE AND MILLING MACHINE) (SPECIFIC)**5.1 Lathe Taper turning**

$$5.1.1 \quad \text{Set-over} = \frac{D-d}{2} \times \frac{\text{Length of workpiece}}{\text{length of taper}}$$

$$= (75-50)/2 \times 400 / 250 \quad \checkmark$$

$$= 12.5 \times 1.6$$

$$= 20 \text{ mm} \quad \checkmark$$



(2)

$$5.1.2 \quad \tan \frac{\theta}{2} = \frac{x}{L} \quad \checkmark$$

$$= 12.5 / 250$$

$$= 0.05$$

$$= \tan^{-1} 0.05 \times 2 \quad \checkmark$$

$$\Theta = 5.724^\circ \quad \checkmark$$

(3)

5.2 Milling Cutters.

- 5.2.1 A – Helical milling cutter ✓
 B – Side and face Cutter/ also Accept Staggered tooth cutter ✓
 C – Dovetail ✓
 D – T-Slot ✓
 E – End mill ✓

(5)

5.3 Cutting Square Threads

$$5.3.1 \quad \text{Lead} = \text{Pitch} \times \text{Number of Starts}$$

$$= 2 \times 12 = 24 \text{ mm} \quad \checkmark$$

(1)

$$5.3.2 \quad \text{Mean Diameter} = \text{OD} - 0,5 \text{ Pitch}$$

$$= 85 - 0,5 \times 12 \quad \checkmark$$

$$= 91 \text{ mm} \quad \checkmark$$

(2)

$$5.3.3 \quad \text{Tan } \theta = \text{Lead} / \pi \times \text{Dm}$$

$$\text{Tan } \theta = 24 / 91 \quad \checkmark$$

$$\Theta = 14,77^\circ \quad \checkmark$$

(2)

5.4 Dividing Head components

A – Index plate: the aim of the index plate is to enable one revolution of the crank to be further subdivided into fractions of a revolution, especially where the fraction is not a factor of 40. ✓

D – Worm-shaft with a Single – start worm engages with a worm gear with 40 teeth. ✓

E – Worm wheel/gear obtain a rotary movement of the spindle. ✓

(3)
[18]

QUESTION 6: TERMINOLOGY (INDEXING) (SPECIFIC)**6.1 GEAR CALCULATIONS:**

6.1.1 Gang Milling: Simultaneously using several cutters of different diameters and forms on the arbor, workpiece can be machined to size in one movement of the milling machine table. ✓ (1)

6.1.2 Straddle Milling: consists of two side and face cutters, separated by spacing collars of required dimensions to produce parallel work in one cut. ✓ (1)

6.2 Procedure to cut external metric V-screw thread using compound slide method

- Set up the workpiece in the centre lathe and turn the part to be threaded to the required diameter of the thread. ✓
- Set the compound slide to 30° to the left of the centre line of that cross-slide and set the cutting tool up accurately in the tool post. ✓
- Consult the index plate of the quick-change gear box and shift the levers accordingly for the necessary pitch of the screw thread. ✓
- Start the centre lathe and set the cutting tool at touching point on the workpiece. ✓
- Move the cutting tool a short distance off, to clear the end of the workpiece and feed the compound slide 0.05 mm inwards. ✓
- With the centre lathe revolving, engage the half nuts at the correct line on the threading dial, putting the first cut of the screw thread in progress. ✓
- Stop the centre lathe and check the screw thread pitch with a screw thread pitch gauge. ✓ (Any 5 x 1) (5)

6.3 Definition of Indexing is the process of evenly dividing the circumference of a circular work piece into equally spaced divisions, such as in cutting gear teeth, cutting splines, milling grooves in the reamers and taps. ✓ (1)

6.4 Milling methods

- Up-cut milling ✓
- Down-cut milling ✓ (2)

6.5 Differential indexing

<i>Hole circles</i>											
<i>Side 1</i>	24	25	28	30	34	37	38	39	41	42	43
<i>Side 2</i>	46	47	49	51	53	54	57	58	59	62	66

<i>Standard change gears</i>										
24 x 2	28	32	40	44	48	56	64	72	86	100

6.5.1 Indexing Required

$$\begin{aligned} \text{Indexing} &= \frac{40}{A} \quad \checkmark \\ &= 40/120 \\ &= \frac{1}{3} \times \frac{22}{22} \quad \checkmark \\ &= 22/66 \end{aligned}$$

Indexing is 22 holes in a 66-hole circle ✓

(3)

6.5.2 Change of gears

$$\begin{aligned} \text{Gear ratio: } \frac{\text{Driver}}{\text{Driven}} &= \frac{A-N}{A} \times \frac{40}{1} \quad \checkmark \\ &= \frac{120-113}{120} \times 40 \quad \checkmark \\ &= +\frac{7}{3} \times \frac{8}{8} \quad \checkmark \\ &= 56/24 \quad \checkmark \end{aligned}$$

The driver gear has 56 teeth

The driven gear has 24 teeth ✓

(5)

6.5.3 The direction of motion is clockwise

The crank handle will turn the same direction as index plate ✓

(2)

6.6 Dove tail Calculations

$\Theta = 40^\circ$

$\alpha = 20^\circ \quad \checkmark$

$$\begin{aligned} x &= r / (\tan \alpha) \\ &= 10 / (\tan 20) \\ &= 27,47 \text{ mm} \quad \checkmark \end{aligned}$$

$$\begin{aligned} X &= 80 + 2R + 2x \quad \checkmark \checkmark \\ &= 80 + 20 + (2 \times 27,47) \quad \checkmark \\ &= 154,94 \text{ mm} \quad \checkmark \end{aligned}$$

(6)

6.7 Types of Milling machines

- Vertical milling machine ✓
- Horizontal milling machine ✓

(2)


[28]

QUESTION 7: TOOLS AND EQUIPMENT (SPECIFIC)

7.1 Hardness Testers

7.1.1 Brinell Hardness tester


The Brinell Hardness Test involves indenting the test material with a piece hardened steel or carbide ball of 10 mm. The diameter of the indentation left in the test material is measured with a low-powered microscope.



✓✓✓ (3)

7.1.2 Rockwell Hardness tester

Rockwell Hardness Test method involves indenting the test material with a diamond cone or hardened steel-ball indenter.




✓✓✓ (3)

7.2 Hardness measure of a metal.

- Resistance to penetration ✓
- Elastic hardness ✓
- Resistance to abrasion ✓

(Any 2 x 1) (2)


7.3 Screw thread micrometre



(5)
[13]

QUESTION 8: FORCES (SPECIFIC)

8.1 Resultant Force Calculations:



$$X_{\text{Com}} = 100 \cos 50 + 80 \cos 40 - 60 \quad \checkmark$$

$$= 65,56 \text{ N} \quad \checkmark$$

(2)

$$Y_{\text{com}} = 100 \sin 50 - 80 \sin 40 - 70 \quad \checkmark$$

$$= 95,18 \text{ N} \quad \checkmark$$

(2)

$$R = \sqrt{X^2 + Y^2}$$

$$R = 115,576 \text{ N} \quad \checkmark$$

$$\tan \theta = y/x \quad \checkmark$$

$$\tan \theta = 95,18/65,56 \quad \checkmark$$

$$\theta = 55,44$$

$$= 55,44^\circ \quad \checkmark$$



Equilibrant = Resultant BUT IN THE OPPOSITE DIRECTION


$$\text{Equilibrant} = 115,567 \text{ N at } 235,44^\circ \quad \checkmark$$

(5)

8.2 Moments

Converting the UDL to Point Load

$$4 \times 10 = 40 \text{ kN @ } 3 \text{ m from the left hand end} \quad \checkmark$$



Calculation the Reactions by taking moments:

CLOCKWISE MOMENTS = ANTICLOCK-WISE MOMENTS

$$(R_c \times 4) + (5 \times 1) = (5 \times 6) + (40 \times 2) + (8 \times 5) \quad \checkmark$$

$$R_c = 36,25 \text{ kN} \quad \checkmark$$

$$(R_B \times 4) + (5 \times 2) + (8 \times 1) = (40 \times 2) + (5 \times 5) \quad \checkmark$$

$$R_B = 21,75 \text{ kN} \quad \checkmark$$

(5)

8.3 Stress Calculations

8.3.1 Tensile Stress Calculations

F = 40 kN; D = 98, d = 67mm: L = 80 mm: E = 90 PGa

$$A = \frac{\pi(D^2 - d^2)}{4} \quad \checkmark$$

$$A = \frac{\pi(0,098^2 - 0,067^2)}{4}$$

$$= 4,02 \times 10^{-3} \text{ m}^2 \quad \checkmark$$

$$\sigma = \frac{F}{A} \quad \checkmark$$

$$\sigma = \frac{40000}{4,02 \times 10^{-3}} \quad \checkmark$$

$$\sigma = 9950248,76 \text{ Pa}$$

$$\sigma = 9,95 \text{ MPa} \quad \checkmark$$

(5)

8.3.2 The Strain calculations

$$\varepsilon = \frac{\sigma}{E} \quad \checkmark$$

$$\varepsilon = \frac{9,95 \times 10^6}{90 \times 10^9} \quad \checkmark$$

$$= 0,11 \times 10^{-3}$$

$$\text{or } 1,11 \times 10^{-4} \quad \checkmark$$

(3)

8.3.3 Change in length

$$\varepsilon = \frac{\Delta l}{l} \quad \checkmark$$

$$\Delta l = \varepsilon \times l \quad \checkmark$$


$$= (0,11 \times 10^{-3}) \times 0,08$$

$$= 8,8 \times 10^{-6} \text{ m}$$

$$= 8,8 \times 10^{-3} \text{ mm} \quad \checkmark$$

(3)

8.4 Stress/Strain diagram



✓ (Diagram shape)

- | | | |
|------------------------------|---|-----|
| A – Limit of Proportionality | ✓ | |
| B – Elastic limit | ✓ | |
| C – Yield point | ✓ | |
| D – Maximum Force/Point | ✓ | |
| E – Point of Fracture | ✓ | (6) |

- 8.5 FOS stands for Factor Of Safety or Safety Factor. ✓✓ (2)
[33]

QUESTION 9: MAINTENANCE



9.1 Material Classifications

- 9.1.1 PVC – Thermoplastic ✓ (1)
- 9.1.2 Glass fibre – Thermo-setting plastic ✓ (1)
- 9.1.3 Nylon – Thermoplastic ✓ (1)

9.2 Reasons for using cutting fluid when working on the centre lathe.

- It prolongs the life of a cutting tool. ✓
- It prevents the shavings or metal chips from sticking and fusing to the cutting tool. ✓
- It will carry away the heat generated by the turning process.
- It flushes away shavings/metal chips.
- It improves the quality of the finish of the turned surface. (Any 2 x 1) (2)

9.3 Gear Drives Maintenance.

- Checking and replenishment of lubrication levels ✓
- Ensuring that gears are properly secured to shafts ✓
- Cleaning and replacement of oil filters
- Reporting excessive noise and wear, vibrations and overheating for expect attention. (Any 2 x 1) (2)

9.4 Reasons for the use of carbon fibre

- It is light in weight. ✓
- It is tougher and stronger. ✓
- It can be bent to any shape when heated above 150 °C. (Any 2 x 1) (2)

9.5 ONE property and ONE use of each composite

Composite		Property	Uses
9.5.1	Teflon	<ul style="list-style-type: none"> • Resistant to water, grease, heat and corrosion ✓ • Needs no lubrication • Very low co-efficient of friction (Any 1) 	Orthopaedic and prosthetic appliances, hearing aids, joints, upholstery, electric insulation and non-stick coating pans ✓ (Any 1)
9.5.2	Vesconite	<ul style="list-style-type: none"> • Withstands high temperatures • self lubrication ✓ • resistant to water, grease heat and corrosion. • good machinability. (Any 1) 	<ul style="list-style-type: none"> • Orthopaedic and prosthetic appliances. ✓ • Hearing aid • Upholstery (Any 1)
9.5.3	Baskelite	<ul style="list-style-type: none"> • heat resistant ✓ • Brittle in nature (Any1) 	<ul style="list-style-type: none"> • Aircraft Components, bearings, brake linings and laminated material ✓ (Any1)

(6)

- 9.6
- Contact pressure ✓
 - Temperature ✓
 - Sliding velocity ✓
 - Type of a lubricant ✓
 - Surface roughness ✓



(Any 3 x 1) (3)

[18]

QUESTION 10: JOINING METHODS (SPECIFIC)**10.1 Square Thread Calculations:**

$$T = 48 \text{ mm} ; m = 3$$

$$10.1.1 \quad \text{PCD} = T \times m \\ = 48 \times 3 = 144 \text{ mm} \checkmark\checkmark \quad (2)$$


$$10.1.2 \quad \text{Add} = \text{Module} = 3 \text{ mm} \checkmark \quad (1)$$

$$10.1.3 \quad \text{Clearance} = 0,157 \times 3 \\ = 0,471 \text{ mm} \checkmark\checkmark \quad (2)$$

$$10.1.4 \quad \text{Ded} = 1,157 \times 3 \\ = 3,471 \text{ mm} \checkmark\checkmark \quad (2)$$

$$10.1.5 \quad \text{OD} = \text{PCD} + 2 \times 3 \\ = 150 \text{ mm} \checkmark\checkmark \quad (2)$$

$$10.1.6 \quad \text{Circular Pitch} \\ = \pi \times m \\ = \pi \times 3 = 9,424 \text{ mm} \checkmark \quad (1)$$

10.2 Left-hand square screw thread

A – Leading Angle \checkmark (1)

B – Following or Trailing Angle \checkmark (1)

C – Clearance \checkmark (1)

D – Helix angle \checkmark (1)

10.3 A multi-start thread allows for a faster travel or movement and is more efficient as it loses less power through friction compared to single start thread. $\checkmark\checkmark$ (2)

10.4 Screw Thread fit is a combination of allowances and tolerances and a measure of tightness or looseness between the bolt and nut. $\checkmark\checkmark$ (2)

[18]

QUESTION 11: SYSTEMS AND CONTROL (DRIVE SYSTEMS) (SPECIFIC)

11.1 Rotational velocity is where a body rotates (spin) around its axis. It is the rotation rate or how fast a body revolves or turns. It is measured in radians per second. ✓✓ (2)

11.2 Hydraulic system calculations**11.2.1 Calculate the Fluid pressure**

$$A_A = \frac{\pi D_A^2}{4} \quad \checkmark$$

$$= \frac{\pi 0.04^2}{4} \quad \checkmark$$

$$= 1,26 \times 10^{-3} \text{ m}^2$$

$$P_A = \frac{F_A}{A_A} \quad \checkmark$$

$$= \frac{275}{1,2566 \times 10^{-3}} \text{ Pa} \quad \checkmark$$

$$= 218844 \text{ Pa} \quad \checkmark$$

$$= 218,84 \text{ kPa} \quad \checkmark$$

(4)

11.2.2 Load on the piston B

$$A_B = \frac{\pi D^2}{4} \quad \checkmark$$

$$= \frac{\pi 0.075^2}{4} \quad \checkmark$$

$$= 4,42 \times 10^{-3} \text{ m}^2$$

$$P_B = \frac{F_B}{A_B} \quad \checkmark$$

$$F_B = P_B \times A_B \quad \checkmark$$

$$= (218,85 \times 10^3) \times (4,42 \times 10^{-3}) \quad \checkmark$$

$$= 967,32 \text{ N}$$

$$\text{Mass} = \frac{967,32 \text{ N}}{10} \quad \checkmark$$

$$= 96,73 \text{ kg}$$

(4)

11.2.3 Hydraulic System Applications

- Machine tools, ✓ motor vehicle, ✓ hydraulic jacks ✓ (Any 2 x 1) (2)

11.3 Hydraulics refers to the transmission and control of forces and movement by means of fluid. Fluid (generally oil) is used to transmit energy. ✓✓ (2)




11.4 Belt Drive Calculations

$$N_{\text{motor}} \times D_{\text{motor}} = N_{\text{blade}} \times D_{\text{blade}}$$

$$130 \times 1205 = 385 \times D_{\text{blade}} \quad \checkmark$$

$$D_{\text{blade}} = 406,883 \text{ pm} \quad \checkmark \quad (2)$$


11.5 Pneumatic symbols

11.5.1	Pump	 Pump ✓✓
11.5.2	Air receiver	 Receiver ✓✓
11.5.3	Filter	 Filter ✓✓

(6)

11.6 Gear-Drive system calculations:

Data:

11.6.1 Rotation speed of Electric motor 

$$\frac{N_{\text{INPUT}}}{N_{\text{OUTPUT}}} = \frac{T_B \times T_D \times T_F}{T_A \times T_C \times T_E}$$

$$N_{\text{INPUT}} = \frac{T_B \times T_D \times T_F}{T_A \times T_C \times T_E} \times N_{\text{OUTPUT}} \quad \checkmark$$

$$N_{\text{INPUT}} = \frac{36 \times 46 \times 60}{18 \times 16 \times 40} \times 160 \quad \checkmark$$

$$= 1380 \text{ r/min} \quad \checkmark$$

(3)

11.6.2 Velocity ratio

$$VR = \frac{N_{\text{INPUT}}}{N_{\text{OUTPUT}}}$$

$$= \frac{1380}{160} \quad \checkmark$$

$$= 8,625:1$$

$$= 8,63:1 \quad \checkmark$$

(2)

11.6.3 Driven will rotate Clockwise ✓

(1)

[28]

TOTAL: 200