



Province of the
EASTERN CAPE
EDUCATION

**NATIONAL
SENIOR CERTIFICATE**

GRADE 12

SEPTEMBER 2020



**MECHANICAL TECHNOLOGY: WELDING AND
METALWORK
MARKING GUIDELINE**

MARKS: 200

This marking guideline consists of 18 pages.

QUESTION 1: MULTIPLE-CHOICE QUESTIONS (GENERIC)

- 1.1 C ✓ (1)
- 1.2 B ✓ (1)
- 1.3 C ✓ (1)
- 1.4 A ✓ (1)
- 1.5 B ✓ (1)
- 1.6 C ✓ (1)
- [6]**

QUESTION 2: SAFETY (GENERIC)

- 2.1 **Gas welding (PPE)**
- Eye protection ✓
 - Overall / leather apron ✓
 - Safety boots ✓
 - Gloves ✓
- (Any 2 x 1) (2)
- 2.2 **Safety rules that must be followed while the surface grinder is in operation:**
- Make sure that the sparks pose no danger to co-workers. ✓
 - Do not force the material onto the grinding wheel. ✓
 - Do not plunge grind. ✓
 - Bring the material slowly into contact with the grinding wheel. ✓
 - Never clean or adjust the machine whilst it is in motion. ✓
 - Use cutting fluid. ✓
 - Know where the emergency stop is located. ✓
 - Stop machine before any adjustment ✓
 - Keep tools clear from moving parts. ✓
- (Any 2 x 1) (2)

- 2.3 **Completing a task on any machine**
Switch the machine off. ✓ (1)
- 2.4 **TWO safety precautions before switching on the angle grinder**
- Make sure that there are no cracks or chips on the disc. ✓
 - Make sure that the emery disc that is fitted is rated above the revolutions at which it is turned by the motor. ✓
 - Make sure that the space between the tool rest and the emery disc does not exceed 3 mm. ✓
 - Ensure that guards are in place ✓
 - When switching on the machine, do not stand in front of it, until it reaches its full speed. ✓
 - Do not force or bump the work piece against the emery disc. ✓
 - Grind only on the front surface of the wheel, not the sides. ✓
 - All grinding machines must have a sign indicating the revolutions at which the spindle rotates. ✓ (Any 2 x 1) (2)
- 2.5 **Importance of a welding helmet**
- To protect your eyes and face from ultra-violet rays and radiation ✓ (1)
- 2.6 **Types of workshop layouts:**
- Process layout ✓
 - Product layout ✓ (2)

[10]

QUESTION 3: MATERIALS (GENERIC)

3.1

MATERIALS	DIFFERENT TYPES OF TESTS		
	Sound	Filing	Bend
Cast iron	Very dull sound ✓	Easy ✓	Cannot bend ✓/ Snaps/breaks ✓/ Fractures easily ✓
Mild steel	Medium metallic sound ✓	Easy ✓	Bends easily ✓

(6)

3.2 **Heat treatment process**

- Is the heating and cooling of metals in their solid state so as to change their properties. ✓

(1)

3.3 **Hardness factors:**

- Workpiece size ✓
- Quenching rate ✓
- Carbon content ✓

(Any 2 x 1) (2)

3.4 **Heat treatment processes:**3.4.1 **Tempering**

- Is a process applied to steel and it relieves the strain induced during the hardening process. ✓
- It decreases the degree of hardness ✓
- It increases toughness ✓
- It reduces brittleness ✓
- It gives steel fine grain structure ✓

(Any 2 x 1) (2)

3.4.2 **Annealing**

- Relieves internal stress ✓
- Softens the metal ✓
- Makes metal ductile ✓
- Refines the grain structure ✓
- Reduces brittleness ✓

(Any 2 x 1) (2)

3.5 **Hardness of steel depends upon**

- Carbon content ✓

(1)

[14]

QUESTION 4: MULTIPLE-CHOICE QUESTIONS (SPECIFIC)

- 4.1 A ✓ (1)
- 4.2 D ✓ (1)
- 4.3 C ✓ (1)
- 4.4 C ✓ (1)
- 4.5 D ✓ (1)
- 4.6 B ✓ (1)
- 4.7 D ✓ (1)
- 4.8 D ✓ (1)
- 4.9 A ✓ (1)
- 4.10 A ✓ (1)
- 4.11 A ✓ (1)
- 4.12 B ✓ (1)
- 4.13 B ✓ (1)
- 4.14 A ✓ (1)



[14]

QUESTION 5: TERMINOLOGY (TEMPLATES) (SPECIFIC)

5.1 **Template loft:** Is the heart of the structural workshop. (2)

5.2 **THREE qualities of a good template loft:**

- Accuracy ✓
- Quietness ✓
- Better lighting ✓
- Separate from main building ✓
- Wooden floor with black matt finish ✓
- Large space to accommodate required work ✓ (Any 3 x 1) (3)

5.3 **Web template**

- Is used to mark out the positions of holes on the webs of the channel iron and girder sections. ✓✓ (2)

5.4 **A steel ring:**


5.4.1 **Dimensions of the required material:**

$$\begin{aligned} \text{Mean diameter} &= \text{Outside diameter} - \text{Plate thickness} \checkmark \\ &= 500 - 30 \checkmark \\ &= 470 \text{ mm} \checkmark \end{aligned}$$


$$\begin{aligned} \text{Mean circumference} &= \pi \times \text{Mean diameter} \checkmark \\ &= \pi \times 470 \checkmark \\ &= 1\,476,55 \text{ mm} \checkmark \end{aligned} \quad (6)$$

5.4.2 **Make a neat sketch of the steel ring indicating the mean diameter, outside diameter and the thickness of the material:**

1476,55 mm of 30 x 30 mm square steel bar is required to fabricate the ring.



5.5 Fillet weld on T-joint:



(6)
[23]



QUESTION 6: TOOLS AND EQUIPMENT (SPECIFIC)**6.1 Uses of the machines****6.1.1 Guillotine**

- To cut sheet metal ✓
 - To cut plate metal ✓
- (2)

6.1.2 Bench grinder

- Hand grinding-cutting tools ✓
 - Sharpening cutting tools ✓
- (2)

6.1.3 Press machine

- Is used to install or remove components such as bearings or bushes in machines or mechanical devices ✓✓
- (2)

6.2 Joining equipment labels:**6.2.1 A – Gauges ✓**

B – Outlet ✓

C – Inlet ✓

D – Bonnet ✓

(4)

- 6.2.2**
- Oxygen regulator ✓ (1)

6.3 Function of stock and dies:

- They are used to cut internal and external threads of the bolt and nut. ✓
- (1)

6.4 Function of regulators:

To reduce the cylinder pressure ✓ to operating or working pressure. ✓ (2)

6.5 Operating principle of plasma cutter:

The process involves creating an electrical channel of ionised gas; ✓ that is the plasma cutter itself, through the work piece that is being cut; ✓ this forms an electric circuit back to the plasma cutter via a grounding clamp; ✓ accomplishing this via air that is blowing towards the work piece through a focused nozzle. ✓

(4)**[18]**

QUESTION 7: FORCES (SPECIFIC)**7.1 Term definition**

7.1.1 **Force:** is an influence which changes or tends to change the state of rest of a body or motion ✓✓

OR

It is often more convenient to think about a “pull” or “push”

(Any 1 x 2) (2)

7.1.2 **Hooke’s law:** Strain is directly proportional to the stress it caused, provided the limit of proportionality is not Exceeded. ✓✓

(2)

7.2 Stress and strain

$$7.2.1 \quad \text{Area} = \frac{\pi D^2}{4}$$

$$= \frac{\pi \times (0,024)^2}{4}$$

$$= 4,525 \times 10^{-4} m^2$$

$$\text{Stress} = \frac{\text{Force}}{\text{Area}}$$

$$= \frac{60 \times 10^3}{4,525 \times 10^{-4}}$$



$$= 132,579 \times 10^6 \text{ Pa} \checkmark$$

(2)

$$7.2.2 \quad \text{Strain} = \frac{\text{Change in length}}{\text{Original length}}$$

$$= \frac{0,22 \times 10^{-3}}{212 \times 10^{-3}} \checkmark$$

$$= 1,038 \times 10^{-3}$$

$$= 1,04 \times 10^{-3} \checkmark$$

(2)

$$7.2.3 \quad \text{Young's modulus of elasticity (E)} = \frac{\text{Stress}}{\text{Strain}} \checkmark$$

$$= \frac{132,58 \times 10^6}{1,04 \times 10^{-3}} \checkmark$$

$$= 127,48 \times 10^9 \checkmark$$

$$= 127,48 \text{ GPa} \checkmark$$

(4)

7.3 Calculations of the reactions, bending moments and shear force

$$\begin{aligned}
 7.3.1 \quad \text{Moments about RL: } RR \times 8 &= (2 \times 4) + (6 \times 5) + (3 \times 6) \checkmark \\
 &= 8 + 30 + 18 \\
 &= 56 \checkmark \\
 RR &= 7 \text{ N } \checkmark
 \end{aligned}$$

$$\begin{aligned}
 \text{Moments about RR: } RL \times 8 &= (3 \times 2) + (6 \times 3) + (2 \times 4) \checkmark \\
 &= 6 + 18 + 8 \\
 &= 32 \checkmark \\
 RL &= 4 \text{ N } \checkmark
 \end{aligned} \tag{6}$$

7.3.2 The bending moments at points A, B and C.


$$\begin{aligned}
 BM_A &= (4 \times 4) = 16 \text{ N } \checkmark \\
 BM_B &= (4 \times 6) - (2 \times 2) - (6 \times 1) = 14 \text{ N } \checkmark \\
 BM_C &= (4 \times 7) - (2 \times 3) - (6 \times 2) - (3 \times 1) = 7 \text{ N } \checkmark
 \end{aligned} \tag{3}$$

7.3.3 Shear forces at points, A, B and C

$$\begin{aligned}
 SF_A &= 4 - 2 = 2 \checkmark \\
 SF_B &= 4 - 2 - 6 = -4 \checkmark \\
 SF_C &= 4 - 2 - 6 - 3 = -7 \checkmark
 \end{aligned} \tag{3}$$




7.3.4




(5)

7.3.5




(5)

7.4



Space diagram = 1 mark ✓



Member	Force	Nature
AD	29 kN ✓	Strut ✓
BD	76 kN ✓	Strut ✓
CD	14 kN ✓	Tie ✓

(11)
[45]

QUESTION 8: JOINING METHODS (INSPECTION WELD) (SPECIFIC)**8.1 Arc welding**

- Rate of rod burning and the progress of the weld ✓
- Amount of penetration and fusion ✓
- The way the weld metal is flowing ✓
- The sound of the arc, indicating correct current and voltage for the particular weld ✓ (Any 2 x 1) (2)

Oxy-acetylene

- Correct flame for the work on hand ✓
- Correct angle of blowpipe and rod, depending on the method being used ✓
- Depth of fusion and amount of penetration ✓
- The rate of progress along the joint ✓ (Any 2 x 1) (2)

- 8.2
- HAZ (Heat-affected zone) ✓
 - Centreline cracks ✓
 - Crater cracks ✓
 - Transverse cracks ✓ (Any 2 x 2) (4)

- 8.3
- A – Penetration ✓
 - B – Width ✓
 - C – Height ✓
 - D – Weld bead ✓
 - E – Base metal ✓ (5)



- 8.4
- Shape of profile ✓
 - Uniformity ✓
 - Overlap ✓
 - Undercutting ✓
 - Penetration bead ✓
 - Root groove ✓ (Any 2 x 1) (2)

- 8.5 8.5.1 **Spatter**
Caused by voltage being too low ✓ or amperage being too high. ✓ (2)

- 8.5.2 **Incomplete penetration**
- The weld bead does not penetrate the full depth of the weld or into the root of the weld. ✓
 - Two opposing weld beads do not inter-penetrate. ✓
 - The weld does not penetrate to the toe of a fillet weld but only bridges across it. ✓ (Any 2 x 1) (2)

8.6 Arc welding

- Rate of rod burning and the progress of the weld ✓
- Amount of penetration and fusion ✓
- The way the weld metal is flowing ✓
- The sound of the arc, indicating correct current and voltage for the particular weld ✓ (Any 2 x 1) (2)

8.7 Testers**8.7.1 Nick-break test is done to:**

Determine the internal quality of the weld metal ✓ and can reveal the internal defects ✓ (2)

8.7.2 Machinability test is done to:

Determine the hardness ✓ and strength ✓ of the welded joint. (2)
[25]



QUESTION 9: JOINING METHODS (STRESSES) (SPECIFIC)**9.1 Term definition**

9.1.1 **Weld distortion:** Takes place in a welded joints due to uneven expansion and contractions ✓ as a result of intense heat of the arc or oxy-acetylene flame. ✓ (2)

9.1.2 **Residual Stress:** Is the internal stress distribution locked into the material; ✓ these stresses are present even after all external loads or forces have been removed. ✓ (2)

9.2 Factors affecting grain size

- The prior amount of cold work ✓
- The temperature and time of the annealing process ✓
- Composition and constitution ✓
- Its melting point ✓ (Any 2 x 1) (2)

9.3	Low carbon steel ✓	0,15 – 0,30% ✓	
	Medium carbon steel ✓	0,31 – 0,70% ✓	
	High carbon steel	0,71 – 1,5%	(Any 2 x 2) (4)


9.4 Quenching mediums

- Brine ✓
- Water ✓
- Oil ✓
- Metal salt ✓
- Air ✓ (Any 2 x 1) (2)

**9.5 Factors affecting shrinkage in welding**


- Size of work piece ✓
- Weld thickness ✓
- Thermal conductive properties of parent metal ✓ (Any 2 x 1) (2)

9.6 9.6.1 Transverse shrinkage



(2)

9.6.2 Longitudinal shrinkage



(2)


[18]**QUESTION 10: MAINTENANCE (SPECIFIC)**

- 10.1 Keeping records assists in upholding warranties and guarantees because service requirements inevitably form part of agreements. ✓ (1)
- 10.2 Due to the danger associated with a large machine, it is critical to isolate the machine completely before any maintenance is undertaken ✓ to ensure nobody can turn on the machine. ✓ (2)
- 10.3 Friction can be reduced by applying cutting fluid or light oil to the drill bit. ✓ (1)
- 10.4 10.4.1 Cutting plate of excessive thickness ✓ or hardness will overload both the blade and hydraulic system. ✓ (2)
- 10.4.2 The feed speed which is higher than the rate at which the power saw can cut, ✓ effectively results in the blade being forced into the materials. ✓ (2)

[8]

QUESTION 11: DEVELOPMENT (SPECIFIC)

11.1 11.1.1



$$\hat{C} = 70^\circ$$

$$EC = BC - BE$$

$$= 2 - 1$$

$$= 1m$$

✓✓✓✓✓

$$\therefore \cos 70^\circ = \frac{EC}{DC}$$

$$DC = \frac{1}{\cos 70^\circ}$$

$$DC = \frac{EC}{\cos 70^\circ}$$

$$DC = 2.92m$$

(5)

11.1.2

$$\cos 70^\circ = \frac{BC}{AC}$$

$$AC = \frac{BC}{\cos 70^\circ} \quad \checkmark\checkmark\checkmark\checkmark$$

$$AC = \frac{2}{\cos 70^\circ}$$

$$\therefore AC = 5.85m$$

(4)

11.1.3

$$\text{Circumf.} = \pi D$$

$$= \pi(4) \quad \checkmark\checkmark\checkmark$$

$$= 12.57m$$

(3)

11.2 Square-to-round transition piece:

11.2.1 The true length FG is firstly needed to draw the pattern.

$$IK = 300(2\text{units})$$

$$IH = 150(1\text{unit})$$

$$HK = 1\sqrt{3} (1\text{unit} \times \sqrt{3})$$

The true length FG:

$$\text{Plan length FG} = FG - GK \quad \checkmark$$

$$= 400 - 300$$

$$= 100 \text{ mm} \quad \checkmark$$

The true FG is equal to H'F

$$H'F^2 = H'G^2 + GF^2 \quad \checkmark$$

$$= 800^2 + 100^2 \quad \checkmark$$

$$H'F = \sqrt{650000} \quad \checkmark$$

$$\text{True length FG} = 806 \text{ mm} \quad \checkmark \quad (5)$$

11.2.2 To determine the plan length CI, the sides CE and EI of triangle CEI must first be calculated.

$$\begin{aligned} CE &= CF - EF \\ &= 400 - 150 \\ &= 250 \text{ mm} \end{aligned}$$

✓

$$\text{But EI} = FH$$

$$\begin{aligned} FH &= FK - HK \\ &= 400 - 259,8 \\ &= 140,2 \text{ mm} \end{aligned}$$

✓

$$\begin{aligned} \text{True length(CI)} &= FH^2 + EI^2 \quad \checkmark \\ &= 250^2 + 140,2^2 \\ &= \sqrt{82156,04} \\ &= 286,63 \text{ mm} \quad \checkmark \end{aligned}$$

(4)
[21]

TOTAL: 200